



High Resolution Hydraulic Profiling and Groundwater Sampling using FLUTe™ System in a Fractured Limestone Setting

Janniche, Gry Sander; Christensen, Anders G.; Groesen, Bernt; Kernn-Jespersen, Henriette; Broholm, Mette Martina

Publication date:
2013

Document Version
Publisher's PDF, also known as Version of record

[Link back to DTU Orbit](#)

Citation (APA):
Janniche, G. S., Christensen, A. G., Groesen, B., Kernn-Jespersen, H., & Broholm, M. M. (2013). *High Resolution Hydraulic Profiling and Groundwater Sampling using FLUTe™ System in a Fractured Limestone Setting*. Abstract from NGWA Conference on Groundwater in Fractured Rock and Sediments, Burlington, Vermont, United States.

General rights

Copyright and moral rights for the publications made accessible in the public portal are retained by the authors and/or other copyright owners and it is a condition of accessing publications that users recognise and abide by the legal requirements associated with these rights.

- Users may download and print one copy of any publication from the public portal for the purpose of private study or research.
- You may not further distribute the material or use it for any profit-making activity or commercial gain
- You may freely distribute the URL identifying the publication in the public portal

If you believe that this document breaches copyright please contact us providing details, and we will remove access to the work immediately and investigate your claim.

HIGH RESOLUTION HYDRAULIC PROFILING AND GROUNDWATER SAMPLING USING FLUTE™ SYSTEM IN A FRACTURED LIMESTONE SETTING

Gry S. Janniche^{1,2}, **Anders G. Christensen**², **Bernt Grosen**³, **Henriette Kerrn-Jespersen**⁴, **Mette M. Broholm**¹

¹DTU Environment, Technical University of Denmark, Kgs. Lyngby, Denmark ²; NIRAS, Allerød, Denmark; ³COWI, Kgs. Lyngby, Denmark; ⁴Capital Region of Denmark, Hillerød, Denmark

Characterization of the contaminant source zone architecture and the hydraulics is essential to develop accurate site specific conceptual models, delineate and quantify contaminant mass, perform risk assessment, and select and design remediation alternatives. This characterization is particularly challenging in deposit types as fractured limestone. The activities of a bulk distribution facility for perchloroethene (PCE) and trichloroethene (TCE) at the Naverland site near Copenhagen, Denmark, has resulted in PCE and TCE DNAPL impacts to a fractured clay till and an underlying fractured limestone aquifer/bedrock. A wide range of innovative and current site investigative tools for direct and indirect documentation and/or evaluation of dense non-aqueous phase liquid (DNAPL) presence were combined in a multiple lines of evidence approach. One scope of the investigations was to evaluate innovative investigation methods for characterization of the source zone hydrogeology and contamination, including FLUTE system hydraulic profiling and Water-FLUTE multilevel groundwater sampling, in fractured bryozoan limestone bedrock.

High resolution hydraulic profiling was conducted in three cored boreholes, placed within a 970 ft² (~90 m²) area, and Water-FLUTES were installed with 12-13 sampling screens in each borehole. Hydraulic profiling by FLUTE liner system provided information with higher discretization than other traditional methods, and supported the individual design of Water-FLUTES for multilevel groundwater monitoring, sampling (under two flow conditions) and analysis. Coring for discrete subsampling was a challenge in the limestone, due to core-loss and potential DNAPL loss caused by high drilling water pressure. Hence, the water-FLUTE data proved to be an essential link in the source zone characterization. The results from the high resolution hydraulic profiling and from the Water-FLUTE multilevel sampling will be presented as well as the experiences obtained.